Bumpy Oak Road near Indian Head Rail Trail

A pond is located in the northeast corner of the Bumpy Oak Road and Indian Head Rail Trail intersection. Mattowoman Creek is in close proximity. The road elevation is only a few feet higher than the water surface elevation of the pond. Heavy rain events cause the pond to rise and overtop the road.